

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No. #211826	
7. Unit Agreement Name	
8. Farm or Lease Name Horacek	
9. Well No. 1	
10. Field and Pool, or Wildcat Wildcat	
12. County McKinley	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL <input type="checkbox"/> GAS <input type="checkbox"/> OTHER - <b>Dry Hole</b>
2. Name of Operator <b>R. A. Crane, Jr.</b>
3. Address of Operator <b>101-2 Petroleum Plaza Bldg., Farmington, N. M. 87401</b>
4. Location of Well UNIT LETTER <b>I</b> <b>2310</b> FEET FROM THE <b>South</b> LINE AND <b>330</b> FEET FROM THE <b>East</b> LINE, SECTION <b>15</b> TOWNSHIP <b>14N</b> RANGE <b>8W</b> NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) <b>7154 GL</b>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

We spotted three cement plugs on this well on October 4, 1971, one from a depth of 813' to 1013', the second from a depth of 460' to 510' and the third plug in the surface pipe, and erected a dry hole marker. A 34" joint of 7" surface pipe was left in this hole. The above plugs were spotted by Stewart Bros. Drilling Company through open ended drill pipe using their mud pump and steel tank for mixing. This location is ready for your inspection.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED W. M. Sullivan TITLE Agent DATE Oct. 7, 1971.  
APPROVED BY Gregory C. Ames TITLE Rep. Dist. III DATE 11-12-71  
CONDITIONS OF APPROVAL, IF ANY: