



STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT
OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE

TONEY ANAYA
GOVERNOR

1000 RIO BRAZOS ROAD
AZTEC, NEW MEXICO 87410
(505) 334-6178

November 15, 1983

Mr. Louis M. Wymon
P. O. Box 278
Craig, CO 81265

Re: Jaco 58 & Jaco 55-Y D-32-20N-9W

Dear Louis:

A recent field inspection of the referenced wells reveals several infractions of NMOCD rules and regulations. Specifically, oil must be skimmed from the pit so production water can evaporate. Pit is seeping water which is running out onto grassland and must be repaired or replaced. Pit fence is sagging and needs to be repaired. Lease is junky and oil stained. You have no well signs.

I will reinspect the lease in about one month. If remedial action has not been initiated, I will shut it in.

If you have any questions, please contact this office.

Yours truly,

Charles Gholson
Deputy Oil & Gas Inspector

CG/ca

cc: Dick Stamets
Arlene Luther, Navajo Nation, Box 308, Window Rock, AZ 86515
Reading file
Well file
Operator file