

NO. OF COPIES RECEIVED	12
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	1
LAND OFFICE	1
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State ☐ Fee ☐

5. ~~SANTA FE R.R. LANDS.~~
Santa Fe R. R. Lands.

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- DRY HOLE.	7. Unit Agreement Name none.
2. Name of Operator Ramsey Petroleum Company.	8. Farm or Lease Name "Cactus Flower"
3. Address of Operator P. O. Box 11446. Albuquerque, N. M. 87112.	9. Well No. 1.
4. Location of Well UNIT LETTER E ; 1500' FEET FROM THE North LINE AND 860' FEET FROM THE West LINE, SECTION 20 TOWNSHIP 17-N. RANGE 7-W. NMPM.	10. Field and Pool, or Wildcat Wildcat.
15. Elevation (Show whether DF, RT, GR, etc.) 6807' Ground.	12. County McKinley.

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Subsequent Report to Notice of Intention to Plug & Abandon dated December 11, 1973.
Dry Hole Marker was installed when drilling rig was moving off location. Cement to surface in Casing. DRY HOLE. Geology by Gene D. Wilson of Albuquerque, N. M.

The wire fence and posts have been removed and pits filled and levelled.

Location has been levelled.

Road graded and levelled.

Location cleaned up.

NOTE: All of the above actions were under the supervision of the Ranch foreman Mr. Orville Moore of Grants, N. M. and have met with his approval.

3-copies Filed.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Arthur Ramsey TITLE Operator. DATE July 3, 1974.
APPROVED BY Ernest E. Wilson TITLE Sup Int. III DATE 9. 23. 74

RAMSEY PETROLEUM CO.

P. O. BOX 11446

ALBUQUERQUE, NEW MEXICO 87112

August 19, 1974

Mr. Dave M. Thomas, Jr.
413 W. Main Street
Farmington, New Mexico 87401

RE: Cactus Flower No. 1
well, Mc-140

Dear Dave,

Mr. Arnold of the New Mexico Oil and Gas Conservation Commission in Aztec advises the dry hole steel post marker is missing from the above well. I advised him that you took care of this matter during the plugging operations and had assured me the post had been installed. Thereafter, we promptly paid the invoice for this marker, copy attached.

Please telephone Mr. Arnold and take care of this matter.
Thank you for your assistance.

Yours truly,

Arthur B. Ramsey

ABR:lo

cc. Mr. Emory C. Arnold
New Mexico Oil and Gas Conservation Commission
1000 Rio Brazos Road
Aztec, New Mexico 87410



RAMSBY PETROLEUM CO.

5701 10th Ave

ALBUQUERQUE, NEW MEXICO 87112

[Faint, illegible text, likely bleed-through from the reverse side of the page]



