NM-7097

5. LEASE

## UNITED STATES , DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME Federal
1. oil gas well other Dry Hole	9. WELL NO.
2. NAME OF OPERATOR	1-20
Damson Oil Company  3. ADDRESS OF OPERATOR	10. FIELD OR WILDCAT NAME Undesignated Entrada
260 N.Belt East, Suite 300, Houston, Texas.	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)	AREA Sec. 20, T16N-R8W
AT SURFACE: 990'/N & 1980'/E	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL:	McKinley New Mexico
at total depth: Same	14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	en a lanc com a company of the compa
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	6760' Ground
TEST WATER SHUT-OFF	(NOTE: Report results of multiple completion or zone change on Form 9-330.)
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly statincluding estimated date of starting any proposed work. If well is a measured and true vertical depths for all markers and zones pertined	firectionally drilled, give subsurface locations and not not to this work.)*
This well was plugged and abandoned on 8/6/7	7. Cement plugs were set
at the following depths: 1. 3494'-3290'	
2. 2100'=1900'	100 19
3. 1300'-1000'	e <sup>1</sup> (a'
4. 600- 400'	received 19 NM
5. 100' in surface.	
A dry hole marker was erected and the locati	on restored. Auguston No.
Subsurface Safety Valve: Manu. and Type	Set @ Ft.
18. I hereby certify that the foregoing is true and correct	
SIGNED W.D. Stricklin TITLE Agent	DATE 8/28/79
(This space for Federal or State of	
APPROVED BY (Orig. Sgd.) RAYMOND W. VINYARD FAYMOND W. VINYARD CONDITIONS OF APPROVAL, IF ANY	ARD DEC 0 1 1981