

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ gas ☐
well well other2. NAME OF OPERATOR
Dome Petroleum Corp.3. ADDRESS OF OPERATOR 501 Airport Drive,
Suite 107, Farmington, N.M. 874014. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17
below.) Sec. 22, T19N, R5W
AT SURFACE: 2100' FSL, 2250' FEL
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,
REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐
(other) ☐☐
☐
☐
☐
☐
☐
☐
☒(NOTE: Report results of multiple completion or zone
change on Form 9-330.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates,
including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and
measured and true vertical depths for all markers and zones pertinent to this work.)*

7/3/78 Plugged and abandoned well as follows:

#1 5100'-5250' 150' 75 sx
#2 4140'-4290' 150' 75 sx
#3 2100'-2250' 150' 75 sx
#4 1930'-2080' 150' 75 sx
#5 175'- 225' 50' 35 sx
#6 0'- 30' 30' 15 sxErected marker and moved off. Location will be cleaned and pit
fenced until dry. The pit will then be closed and the location
seeded as specified by BLM.

Subsurface Safety Valve: Manu. and Type _____

Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED

J. Arnold Snell
J. Arnold Snell

TITLE

Drilling & Production
Superintendent

DATE

July 3, 1978

(This space for Federal or State office use)

APPROVED BY _____

TITLE _____

DATE _____

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

JUL 24 1978

*See Instructions on Reverse Side

U. S. GEOLOGICAL SURVEY