UNITED STATES	5. LEASE TOOK	—
DEPARTMENT OF THE INTERIOR	5. LEASENM-7095	
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	7. UNIT AGREEMENT NAME	
	8. FARM OR LEASE NAME	
1. oil gas other Dry Hole	Federal 9. WELL NO.	
2. NAME OF OPERATOR Damson Oil Company	1-24	
	10. FIELD OR WILDCAT NAME Undesignated Entrada	
3. ADDRESS OF OPERATOR 260 N. Belt east, Houston, Texas 77060	11. SEC., T., R., M., OR BLK. AND SURVEY	V OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)	AREA Sec. 24, t15N-R8W N.M.P	
AT SURFACE: 330° /N & 1650° /E AT TOP PROD. INTERVAL:	12. COUNTY OR PARISH 13. STATE New Mex	 :icc
at total depth: Same	14. API NO.	
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA		
	15. ELEVATIONS (SHOW DF, KDB, AND 6698 Ground	WD)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:		
TEST WATER SHUT-OFF		
SHOOT OR ACIDIZE		
REPAIR WELL	(NOTE: Report results of multiple completion or	zone
PULL OR ALTER CASING MULTIPLE COMPLETE	change on Form 9–330.)	
CHANGE ZONES		
ABANDON* (other)		
(Other)		
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly statincluding estimated date of starting any proposed work. If well is considered to the control of t	te all pertinent details, and give pertinent d	ates,
measured and true vertical depths for all markers and zones pertine	nt to this work.)*	
M14		
This well was plugged and abandoned	on November 17, 1977.	
Cement plugs were set at the follow:	rus gebrus:	
2. 2400: -2550:		
3: 21.50:-2300:	A STATE OF THE STA	

- 11501-13001
- 1001 in surface.

A dry hole marker was erected and the location restored.

Subsurface Safety Valve: Manu. and Type ___ 18. I hereby certify that the foregoing is true and correct TITLE Agent DATE (This space for Federal or State office use) APPROVED BY CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side