UNITED STATES

UNITED STATES	
	5. LEASE & 5 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2
DEPARTMENT OF THE INTERIOR	NM 0555838 A ₩ ₩ ₩ ₹ 5
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
	5 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME: 8 4 4 5 4 5 4 5 5 6 5 6 5 6 5 6 5 6 5 6 5
Do not use this form for proposals to drill or to deepen or plug back to a different eservoir. Use Form 9-331-C for such proposals.)	iner
eservoir, Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME និង ខ្លាំង និង និង និង និង និង និង និង និង និង និ
1. oil gas	Star CERE E STE
well well other	9. WELL NO. 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2
2. NAME OF OPERATOR	9. WELL NO. 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
Basin Fuels, Ltd.	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR	Franciscian Lake Mesa Verde
	11. SEC., T., R., M., OR BLK. AND SURVEY OR
300 W. Arrington, Suite 300, Farmington, NM	AREA REPORTER AND SERVET OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	Sec 7, T20N, R5W
below.) AT SURFACE: 660' FSL & 330' FWL	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL:Same	
AT TOTAL DEPTH: Same	McKinley New Mexico
June	14. API NO. 19.4 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
	6730 GL≨ ៦៩៣ គឺ ង្គីទី៩
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	
FRACTURE TREAT	1 0 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
FRACTURE TREAT	LU PARE E SEE
SHOOT OR ACIDIZE	STA ROTE
REPAIR WELL UN 2018	C (NOTE: Report results of multiple completion or zone
PULL OR ALTER CASING	change on Form 9-330.)를 필요되기
MULTIPLE COMPLETE U U. S. GEOLOGICAL :	SURVEY PRINT DIESE B.
FARMING CON N	
RBANDON	
(other)	ကြောင်းသည်။ မြောက်ကြီးသည်။ မြော်ရှိနှို့ရေးသည်။
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state	all pertinent details, and give erricent dates.
including estimated date of starting any proposed work. If well is di	irectionally drilled, give subsurface for ations and
measured and true vertical depths for all markers and zones pertinen	t to this work.)*
3-18-80 MIRURT Western Drilling Company. S	pud well at 5:30 pp.m. Drift.
12 1/4" hole to 91 feet. Set 8 5/8"	
Cement with 75 sacks Class "B" + 2%	
16 sacks. Plug down 10:30 p.m. 3-18	-80. WOC 12 hours. Nipple
10 Sacks. Pluy down 10.30 p.m. 3-10	-00. WOU IZ HOURS. HTTPLEE
up BOP. Pressure test to 800 psi fo	
constant.	
ACCEPTED FOR RECORD	
Maria Control of the	JUN 22-0 1980 2 2 2 2 2
JUN 27 1 980	
000 100	U. S. GEOLOGICALE SUNTEY STAFF
Subaurface Safety Valve: Many and Type FASHINGTON DISTRICT	DURANGO, COLO.
Subsurface Safety Valve: Manu. and TypeFARKINGTON BISTON	
18. I hereby certify that the foregoing is true and correct	그 사람들은 사람들이 얼굴했습니다.
	7000 T000
SIGNED Jack D. COOKTITLE Agent	DATEUNE 19.1980 =-
(This space for Federal or State office use)	
(1111) appear for 1 cools of otate offi	기계의 보유한호를 되고 영원로
APPROVED BY TITLE	DATE
CONDITIONS OF APPROVAL, IF ANY:	등 등 등 등 등 등 등 등 등 등 등 등 등 등 등 등 등 등 등
	·
NMOCO	
* * * * * * * * * * * * * * * * * * *	N 위문보다 봤 국장중