

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ well gas ☐ well other ☐

2. NAME OF OPERATOR  
WTR Oil Company

3. ADDRESS OF OPERATOR Farmington NM 87401  
c/o Mark E. Weidler, 3005 Northridge Dr. #H

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  
AT SURFACE: 350' FEL, 330' FSL  
AT TOP PROD. INTERVAL: same  
AT TOTAL DEPTH: same

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐  
FRACTURE TREAT ☐  
SHOOT OR ACIDIZE ☐  
REPAIR WELL ☐  
PULL OR ALTER CASING ☐  
MULTIPLE COMPLETE ☐  
CHANGE ZONES ☐  
ABANDON\* ☐

(other) Surface rehabilitation

SUBSEQUENT REPORT OF:

RECEIVED  
DEC 23 1982

U.S. GEOLOGICAL SURVEY  
FARMINGTON, NM

5. LEASE  
NM - 13053 - A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME  
Federal

9. WELL NO.  
1

10. FIELD OR WILDCAT NAME  
Wildcat

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA  
Sec. 9, T18N-R12W NMPM

12. COUNTY OR PARISH  
McKinley

13. STATE  
NM

14. API NO.  
30-031-20660

15. ELEVATIONS (SHOW DF, KDB, AND WD)  
64.4

NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

2/2/81: Well was plugged and abandoned in following manner:

Surface to 140' - 35 sacks  
270' to 570' - 70 sacks  
1110' to 1400' - 80 sacks  
2050' to 2220' - 50 sacks

*Not Approved of SRA*

4/30/81 Pits leveled and location cleaned up  
5/19/81 Dry hole marker set  
8/4/81 Location and road seeded by W & C Contracting  
9/23/81 Location releveled at BLM request. Put in windrows and water bars across road. Re-seed location and road. All work completed and location ready for inspection.

Subsurface Safety Valve: Manu. and Type \_\_\_\_\_ Set @ \_\_\_\_\_ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Mark E. Weidler TITLE Consultant Geologist DATE 12/21/82  
Mark E. Weidler

(This space for Federal or State office use)

APPROVED BY ACCEPTED FOR RECORD TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

DEC 2 1982

BY 44  
FARMINGTON

\*See Instructions on Reverse Side

OPERATOR

RECEIVED