

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

6. LEASE DESIGNATION AND SERIAL NO.

NM 13163

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Wexpro 11

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Wildcat

11. SEC., T., R., M., OR BLE. AND
SURVEY OR AREA

11-15N-11W-NMPM

12. COUNTY OR PARISH 13. STATE

McKinley Co.

NM

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

HIGH PLAINS PETROLEUM CORPORATION

3. ADDRESS OF OPERATOR

%Morris B. Jones, 1223 Bank of New Mexico Bldg., Alb, NM-87101

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)

At surface

660' fnl and 1980' fel

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RL, OR, etc.)

7790 Gr.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

(Other) Subsequent Drilling operations


(NOTE: Report results of multiple completion or Well Completion or Recompletion Report and Log form.) ☒

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Drilled 6 3/4" hole to 2310' TD. Ran logs(DIL, FDC and CNL) to total depth.

Ran DST #1(straddle) from 2197 to 2215.

Slight blow of air through out test. Recovered 717' of water. Init. flow 40 psi to 253 psi, isi 410 psi to 460 psi, second flow 259 psi to 377 psi, second shut-in 416 psi to 488 psi. Plan to P & A.



ACCEPTED FOR RECORD

18. I hereby certify that the foregoing is true and correct

SIGNED

Morris B. Jones

TITLE Morris B. Jones, Engineer

DATE JUN 8 1981

(This space for Federal or State office use)

FARMINGTON DISTRICT

APPROVED BY

TITLE

BY

DATE

CONDITIONS OF APPROVAL, IF ANY:

NMOCC

*See Instructions on Reverse Side