

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ well ☐ gas well ☐ other ☒ Dry Hole

2. NAME OF OPERATOR  
Champlin Petroleum Company

3. ADDRESS OF OPERATOR  
P.O. Box 1257, Englewood, CO 80150

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  
NW NE SE - 2310' FSL, 990' FEL

AT SURFACE:  
AT TOP PROD. INTERVAL:  
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐  
FRACTURE TREAT ☐  
SHOOT OR ACIDIZE ☐  
REPAIR WELL ☐  
PULL OR ALTER CASING ☐  
MULTIPLE COMPLETE ☐  
CHANGE ZONES ☐  
ABANDON\* ☐  
(other) ☐

SUBSEQUENT REPORT OF:

☐  
☐  
☐  
☐  
☐  
☐  
☐  
☒

U. S. GEOLOGICAL SURVEY  
FARMINGTON, N. M.

Verbal approval given by Dean Elliott  
July 2, 1981

5. LEASE

NM-13952

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Star Lake Federal 43A-28

9. WELL NO.

1

10. FIELD OR WILDCAT NAME  
Wildcat/Estrada

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Section 28, T20N, R6W

12. COUNTY OR PARISH

McKinley

13. STATE

New Mexico

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Well was plugged & abandoned 7-3-81 as follows:

1. Spotted plug #1 5490-5590 w/35 sx
2. Spotted plug #2 4400-4500 w/50 sx
3. Spotted plug #3 3370-3470 w/50 sx
4. Spotted plug #4 2270-2370 w/55 sx
5. Spotted plug #5 1430-1530 w/50 sx
6. Spotted plug #6 350-450 w/50 sx
7. Spotted plug #7 130-10' below surface w/40 sx
8. Installed dry hole marker
9. Pits backfilled
10. Surface rehabilitation and seeding completed 8/20/81.

Subsurface Safety Valve: Manu. and Type

18. I hereby certify that the foregoing is true and correct

Approved as to plugging of the well bore.

Liability under bond is retained until surface restoration is completed.

TITLE Sr. Engr. Aide DATE August 20, 1981

This space for Federal or State office use

TITLE DATE

NMOCC

RECEIVED

NOV 26 1984

OIL CON. DIV.  
DIST. 3

APPROVED  
AS AMENDED

151 J. Stan McKee

M. MILLENBACH  
AREA MANAGER