



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Alcarilla Indians

Contract #77

Lease No. _____

Unit Tract 151, T-23-S 1-3-4
Sections 7, 10, 15, & 16

Tract No. 156396

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	<u>Subsequent report of plug-back</u>	<u>1</u>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Alcarilla Indians
INDIAN

August 26, 1954

Well No. 1 is located 990 ft. from N line and 1140 ft. from E line of sec. 15

1/4 of 1/4 of sec. 15 (1/4 Sec. and Sec. No.) 23 (Twp.) 5 (Range) _____ (Meridian)

Alcarilla (Field) Alcarilla (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is will be forwarded later.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Plugged back from 7658 to 7458 feet, 200 feet, with 94 sacks West cement. Plug in place 12:20 A.M., 8-22-54.

Plugged back from 6750 to 6700 feet, 250 feet, with 110 sacks West cement. Plug in place 1:22 A.M., 8-22-54.

Now sitting on cement.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Alcarilla Oil & Refining Company

Address Box 2347

Alcarilla, New Mexico

By M M Rozen

Title District Superintendent

