

Santa Fe

Land Office

SF 078360

Lease No.

Unit

	X	
14		

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

December 22, 61

Nancy B.

Well No. **1-14** is located **970** ft. from **N** line and **1850** ft. from **E** line of sec. **14**
NW NE Sec. 14 **23N** **7W** **NMPN**
 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Undesignated **Rio Arriba** **New Mexico**
 (Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **7087** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Tested casing with 3,000 psi for 30 mins, no pressure drop. Spotted 250 gals. of MCA & Perf. from 5514-5530 w/4 SPT. SWF w/40,000# sand & 40,700 gals. water. BD 3400 psi, Avg. TP 2200 psi, Final pressure 1000 psi, Avg. I.R. 30 NPM. Ran 176 jts. of 2-3/8", 4.7#, J. tbg. TN 5556' set at 5566'. R.R. at 12 noon, 12-21-61.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Val R. Reese & Associates, Inc.

Company

Address Lobby of Sims Building

Albuquerque, New Mexico

Original Sign

By MORRIS B. JONES Morris B. Jones

Title Engineer