

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Budget Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

SF 078272

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	
2. NAME OF OPERATOR BCO, INC.	
3. ADDRESS OF OPERATOR 135 Grant, Santa Fe, N.M. 87501	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 660 FSL 660 FWL Section 10 T23N R7W NMMP	
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 7299 GR

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Dunn

9. WELL NO.

2E

10. FIELD AND POOL, OR WILDCAT

Basin Dakota

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec 10 T23N R7W NMMP

12. COUNTY OR PARISH

Rio Arriba

13. STATE

N.M.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
(Other) <input type="checkbox"/>	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
(Other) Long Term Shut In <input type="checkbox"/>	X

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

On October 5, 1989, Leonard Bixler of the BLM witnessed a Bradenhead Test of Casing Integrity. Before the test the casing had 1200 pounds on it and the tubing had 1500 pounds on it. A puff of gas was detected when the Bradenhead was opened. There was no further gas or flow of any kind. The pressures on the tubing and pressure remained constant.

We, hereby, request an additional year's shut in because the well is unable to produce in paying quantities under current market conditions. The well also produces sulphur water that would have to be appropriately disposed of to meet environmental standards. Present pricing will not economically permit disposal of sulphur water.

RECEIVED

JAN 02 1990

OIL CON. DIV.
DIST. 3

THIS APPROVAL EXPIRES

OCT 26 1990

18. I hereby certify that the foregoing is true and correct

SIGNED Elizabeth B. Keeshan TITLE Vice President

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____
CONDITIONS OF APPROVAL, IF ANY:

APPROVED	
DATE	10/13/89
DATE	DEC 28 1989
AREA MANAGER FARMINGTON RESOURCE AREA	

*See Instructions on Reverse Side
NM000