

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER		5. LEASE DESIGNATION AND SERIAL NO. Tribal #167
2. NAME OF OPERATOR Amerada Hess Corporation		6. IF INDIAN, ALLOTTEE OR TRIBE NAME Jicarilla Apache
3. ADDRESS OF OPERATOR Drawer D, Monument, New Mexico 88265		7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 990' FEL and 790' FNL, Sec. 11, T23N, R3W, Rio Arriba County, New Mexico. Southeast Lindrith Area.		8. FARM OR LEASE NAME J. Apache "I"
14. PERMIT NO.		9. WELL NO. 1
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 7228' DF, 7219' GR, 7229' KB.		10. FIELD AND POOL, OR WILDCAT South Blanco Pictured Cliff
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 11, T23N, R3W, NMPM, Southeast Lindrith Area
		12. COUNTY OR PARISH Rio Arriba
		13. STATE N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

3-10 to 3-17-89

MIRU pulling unit, removed well head & installed BOP. Released trt. pkr. & TOH w/tbg. & pkr. TIH w/RBP & RTTS pkr. on 2-3/8" tbg. Set RBP at 2972' & pkr. at 2941'. Tested BP to 1000#. Held OK. Re-set pkr. at 2817'. Swab Kirtland Sand Zone & recovered 25 b.w. & some gas but would not flow. There was no indication of csg. leak or communication with Pictured Cliffs Zone. TOH w/RBP & RTTS pkr. TIH w/1 jt. 2-3/8" tailpipe, new Halliburton R-4 trt. pkr. & 96 jts. 2-3/8" tbg. Set pkr. at 2995'. Swabbed Pictured Cliffs Zone & recovered 4 b.w. Pictured Cliffs Zone flowing. Kirtland TA'd.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE District Superintendent

DATE 4-14-89

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD

APR 15 1989

FARMINGTON RESOURCE AREA

RV

*See Instructions on Reverse Side

NMOCC