



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Jicarilla Indians
Lease No. Contract No. 39
Unit _____
Co. Loc. 163112

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	<u>Report of drill stem test</u>



(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

**Jicarilla Apache Tribe
of Indians "C"**

Hobbs, New Mexico May 19, 1955

Well No. 1 is located 814 ft. from N line and 951 ft. from E line of sec. 4

SW/4 of SW/4 of Sec. 4 23-N 5-W NMPM
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

Wildcat Sio Arriba New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is Later ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Drill stem test #6 on May 15, 1955 from 5538 to 5598 feet: Tool open 45 minutes, weak blow of air for 21 minutes. One-inch top and 3/4-inch bottom choke. Initial and final mud 2710#. Minimum and maximum flow 0#. Build up pressure after 30 minutes shut in 0#. Recovered 10' drilling mud. No shows.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Humble Oil & Refining Company

Address Box 2347

Hobbs, New Mexico

By [Signature]

Title District Superintendent