

(SUBMIT IN TRIPLICATE)

Indian Agency ... ~~_____~~

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allottee Jearilla Tribal

Lease No. _____ 39

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	Subsequent Report of Sandfrac Treatment

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

November 25 19 **59**

Well No. H-7 is located 990 ft. from S line and 990 ft. from W line of sec. 6

SW/4 SW/4 Sec. 6 23N 5W N.M.P.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

Ballard PC Rio Arriba New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6658 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

10-12-59 TD 2160' NKB. Cleaned out to 2115'. Perforated 2030-68' with 4 shots per foot. Sandfraced with 27,700 gallons water and 40,000# sand, flushed with 4,200 gallons water. Breakdown pressure 1500#, treating pressure 1500-1800#, average injection rate 67 barrels per minute. Dropped 40 rubber balls during treatment.

10-17-59 After 5 days flowing at rate of 83 MCF/day.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be performed.

Company **ARIZONA EXPLORATIONS INC.**

Address **417 Meadows Building**

Dallas 6, Texas

By

Title Vice-President

