Form 9-831a. (Feb. 1951)				

(SUBMIT IN TRIPLICATE)5

Land Office SP				
Lease No.	078555			
Unit				

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Unit ____

SUNDRY	NOTICES	AND	REPORTS	ON	WELLS
SUNDRI	MOTICES	7712			

rep 10 1467

NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	 SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	 SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	 SUPPLEMENTARY WELL HISTORY

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

	Feb. 8.,, 1962.
Well No.2. Pipkin is locate	d 1530 ft. from S line and 510 ft. from W line of sec. S 1
swk Sec. 1	(Twp.) (Range) (Meridian) Range (State of Territory)

The elevation of the derrick floor above sea level is 6881 ftGR.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Set 100 ft plug 2284 to 2184 Shot pipe off at 1200' Set 100' plug on nub. Set 5 sack plug in top of surface Installed marker.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.		
Company Hugh McMillan		
Address 4201 Alabama		
	By J. Harris Title Geologist	
	GPO 918507	