

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office \_\_\_\_\_  
Lease No. 4754-8  
Unit \_\_\_\_\_

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	X
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

January 13, 1958

Well No. 1 is located 1000 ft. from N line and 1000 ft. from W line of sec. 3


1 of sec. 3 (1/4 Sec. and Sec. No.)  
1-1 (Twp.)  
1-1 (Range)  
1-1 (Meridian)  
1 (Field) in 1 (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 574 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Drilled 12" hole to 1379' and cemented 131' of 5/8" casing at 1329' with 175 lbs of cement. Cement job 131' to 1379'. Top of cement job. Actual casing to be cemented for 131' to 1379'.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company The Texas Survey

Address Box 11

Minerton, New Mexico

By [Signature]

Title Contractor