\$ 1000 COLUMN

STATE OF NEW MEXICO



ENERGY, MINERALS and NATURAL RESOURCES DIVISION OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE

BRUCE KING GOVERNOR ANITA LOCKWOOD CABINET SECRETARY 1000 RIO BRAZOS ROAD AZTEC, NEW MEXICO 87410 (505) 334-6178

December 13, 1993

Mr. Bud Crane
Dugan Production Corporation
PO Box 420
Farmington, NM 87499

RE: Illegal Pits in Northwest New Mexico

Sapp C #3, O-05-23N-07W (Tank Drain and Separator pits)

Sapp C #1, M-05-23N-07W (Tank Drain)

Dear Bud:

Field inspections conducted on December 10, 1993 by Charles Gholson revealed that the above mentioned pits have been cleaned as per requested. The pits are now in compliance and the approved C-134's are attached.

If you have any questions please feel free to call me at 505-334-6178.

Yours truly,

Diama K. Jawkwist

Dianna K. Fairhurst

Deputy Oil & Gas Inspector

xc: Don Ellsworth - BLM Farmington

C-134 Correspondence

Well File

1 File

Submit 4 Copies to Appropriate District Office State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-134 Aug. L, 1969

DISTRICT I P.O. Box 1980, Hobbs, NM 88241-1980 OIL CONSERVATION DIVISION P.O. Box 2088

P.O. Drawer DD, Artesia, NM 88211-0719

- Santa Fe, New Mexico 87504-2088

Permit No. 1998
(For Division Use Only)

3 **1993**

DEPUTY OIL & GAS INSPECTOR

DISTRICT III 1000 Rio Brazos Rd., Azzec, NM 87410

Date Facility Inspected 7/15/93

NOT APPROVED -

Inspected by ___

DGF

31 OH & THUNKO NET

APPLICATION FOR EXCEPTION TO DIVISION ORDER R-8952 FOR PROTECTION OF MIGRATORY BIRDS Rule 8(b); Rule 105(b), Rule 312(h), Rule 313, or Rule711(I) DUGAN PRODUCTION CORP. Operator Address: P.O. Box 420, Farmington, NM 87499 M-5-23N-7W Sapp C #1 Lease or Facility Name Location Ltr. Sec. Twp. Rae approx. 10' x 10' TANK DRAIN Size of pit or tank: Operator requests exception from the requirement to screen, net or cover the pit or tank at the above-described facility. The pit or tank is not hazardous to migratory waterlowl. Describe completely the reason pit is non-hazardous. Pit is not large enough to attract migratory waterfowl, generally does not contain fluid, and generally does not contain hazardous material. If any oil or hydrocarbons should reach this facility give method and time required for removal: 1) Oil or hydrocarbons requiring removal will be removed in the most efficient manner dependent upon variable circumstances. Most likely_a vacuum truck will be used within 72 hours of the occurrence. If any oil or hydrocarbons reach the above-described facility the operator is required to notify the 2) appropriate District Office of the OCD with 24 hours. Operator proposes the following alternate protective measures: OCT 1 61989 OIL CON. DIV. CERTIFICATION BY OPERATOR: I hereby certify that the information given above is true and complete to the best of my knowledge and belief. Geologist 10-2-89 Date Title Signature Jim L. Yacobs Telephone No. 505-325-1821 Printed Name 12/10/93 PIT HAG BEEN CLEANED FOR OIL CONSERVATION DIVISION USE PER CG Sainhurst

Approved by

Title

Date