

well file
PETROLEUM ENGINEERING
RESERVOIR STUDIES
EVALUATIONS
GEOLOGICAL STUDIES

EWELL N. WALSH, P.E.
President

WALSH
ENGINEERING & PRODUCTION
CORPORATION
EXECUTIVE BLDG. - 413 W. MAIN
P. O. BOX 254
FARMINGTON, NEW MEXICO
87401

LEASE MANAGEMENT
CONTRACT PUMPING
DRILLING SUPERVISION
WORKOVER SUPERVISION

TELEPHONE 325-8203

February 23, 1973

Mr. Emery Arnold
New Mexico Oil Conservation Commission
1000 Rio Brazos Road
Aztec, New Mexico 87410

Ref: Chace Oil Company, Inc.
Jicarilla No. 71-2
K-Sec. 3-T23N-R4W
Rio Arriba County, New Mexico

Dear Mr. Arnold:

The Initial Deliverability Test Report for the above-referred-to well has not been presented for the following reasons.

1. Producing condition of the well has prevented a successful test being conducted.
2. Sufficient flow of measurable gas during a full chart period (192 hours) has not been available.
3. Well has been shut-in for pressure build up in attempt to clean well up, from water production, sufficiently to conduct an Initial Deliverability Test.
4. Present plans are to perform work on well in attempt to eliminate or decrease flow of water into well bore.

If you have any further questions, please do not hesitate to call upon me.

Very truly yours,

Ewell N. Walsh
Ewell N. Walsh, P. E.
President

ENW:lt

cc:Chace Oil Co.

