

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 23050 -

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

South Blanco 6

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

Lybrook Gallup Ext.

11. SEC., T., R., M., OR BLE. AND
SURVEY OR AREA

Sec. 6-T23N-R7W

12. COUNTY OR PARISH 13. STATE

Rio Arriba

New Mexico

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

6984' GL

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)OIL WELL ☒ GAS WELL ☐ OTHER ☐

NAME OF OPERATOR

Mesa Petroleum Co.

ADDRESS OF OPERATOR

1660 Lincoln Street Suite 2800, Denver, CO 80264

LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*

See also space 17 below.)

At surface

330' FNL & 1660' FEL

14. WELL NO.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) Spud, cement & test BOP ☒REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)*

This well spudded at 2:30 PM 12/1/80. A 12 1/4" hole was drilled to 284'. Six joints of 8 5/8" 24#/ft STC K-55 (New) casing was set at 269' KB. Cemented with 190 sacks Class "B", 2% CaCl. Plugged down at 9:30 PM & circulated 10 barrels of cement to the surface. Tested BOP to 1000 psi and held 30 minutes - OK.



I hereby certify that the foregoing is true and correct

SIGNED

TITLE Division Drilling Supervisor DATE 12/3/80

(This space for Federal or State office use)

APPROVED BY

ACCEPTED FOR RECORD

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

DEC 09 1980

FARMINGTON DISTRICT *See Instructions on Reverse Side

NMOCC