

Form 9-331
(May 1933)UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE
(Other: ~~submit in duplicate~~ or ~~submit in triplicate~~)Form approved
Budget: Budget No. 42-R162
5. LEASE DESIGNATION AND SERIAL NO.
SF-078272

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different well. Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

BCO, Inc.

3. ADDRESS OF OPERATOR

135 Grant Ave. Santa Fe, New Mexico 87501

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface

990' FNL 1840' FWL Sec. 9 T23N R7W

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, CR, etc.)

GR 7207

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Dunn

9. WELL NO.

5

10. FIELD AND FORM. OF WILDCAT

Lybrook Gallup

11. SEC., T., R., M. OR BLK. AND SURVEY OR AREA

Sec. 9 T23N R7W

12. COUNTY OR PARISH

Rio Arriba

13. STATE

N. M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐
☐
☐
☐
☐

PULL OR ALTER CASING

☐
☐
☐
☐
☐

FRACTURE TREAT

MULTIPLE COMPLETION

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐
☐
☐

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) Drilling Progress

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

☐
☐
☐
☒

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)


17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zone pertinent to this work.)

6-30-81 Notified Ray Swanson with the USGS we intend to cement surface pipe on this well between 3:00 and 6:00 P.M.

6-30-81 Drilled 12 1/4" hole and ran 207' 23 # 8 5/8" ERW surface pipe. Cemented with 150 sacks Class B 3% CaCl cement at 5:15 P.M. Circulated 7 barrels of cement to surface.

7-1-81 Spudded 7 7/8 hole after waiting at least 8 hours. Drilling at 383 at 6:00 A.M.

7-2-81 Drilling at 2540.



18. I hereby certify that the foregoing is true and correct

SIGNED Harry R. BylerTITLE PresidentDATE July 2, 1981

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE _____

at

NMOC