

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ well gas ☐ well other ☐
2. NAME OF OPERATOR
CHACE OIL COMPANY, INC.
3. ADDRESS OF OPERATOR
313 Washington SE Albuquerque, NM 87108
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) Unit "B" 805' FNL and 2310' FEL
AT SURFACE:
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:


- TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐
(other) Spud Well

SUBSEQUENT REPORT OF:

- ☐
☐
☐
☐
☐
☐
☐
☐
☐
☐

5. LEASE
Jicarilla 71
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
Jicarilla Apache
7. UNIT AGREEMENT NAME
8. FARM OR LEASE NAME
Jicarilla 71
9. WELL NO.
6
10. FIELD OR WILDCAT NAME
South Lindrith Gallup Dakota
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 3 T23N R4W
12. COUNTY OR PARISH
Rio Arriba
13. STATE
New Mexico
14. API NO.
15. ELEVATIONS (SHOW DF, KDB, AND WD)
7171' GR

(NOTE: Report results of multiple completions or zone change on Form 9-330.)



17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

11/07/81 Moved in Four Corners Rig #10. Rigged up. Spudded 1PM. Ran 5 joints 8-5/8" 23# casing. 212.20' set at 224.00' KB. Cemented with 140 sxs Class "B", 3% calcium chloride, 1 1/2# flow seal per sack. Circulated 2 bbls cement to surface. Plug down 6:45 PM

11/08/81 Drilling at 300'. Bit #2 MW 8.9 Vis. 38 WL 8.0 Oil 10% Tripped for Bit #3 at 1270'.

11/09/81 Started drilling cement at 6:45 AM. Drilling new 7-7/8" hole at 7:45 AM. Tripped for Bit #4 at 2285'.

11/10/81 Drilling at 3198'. Bit #5 MW 8.6 Vis 40 WL 5.0 Oil 5% 3% LCM

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Royce McCarry TITLE President DATE November 11, 1981

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____
CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD

NOV 17 1981

*See Instructions on Reverse Side

BY SAN

MMCCC