

## SUNDRY NOTICES AND REPORTS ON WELLS

1. oil ☒ gas ☐ other

2. NAME OF OPERATOR  
Chace Oil Company, Inc.

### 3. ADDRESS OF OPERATOR

313 Washington, SE, Albuquerque, NM 87108

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) Unit "I" - 1850' EST. c 700' EST.

AT SURFACE:  
AT TOP PROD. INTERVAL:  
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,  
REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐  
FRACTURE TREAT ☐  
SHOOT OR ACIDIZE ☐  
REPAIR WELL ☐  
PULL OR ALTER CASING ☐  
MULTIPLE COMPLETE ☐  
CHANGE ZONES ☐  
ABANDON\* ☐  
(other) *status* ☒

~~SUBSEQUENT REPORT~~

x

U. S. GEOLOGICAL SURVEY  
FARMINGTON, N. M.

**NOTE:** Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

This sundry is to correct the field name to Chacon Dakota on all previous forms. There are no perforations or completions in the Pictured Cliffs, and no intention to perforate the Pictured Cliffs at this time.

Subsurface Safety Valve: Manu. and Type \_\_\_\_\_ Set @ \_\_\_\_\_ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Z. W. Muller TITLE President DATE 1/21/83

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
 CONDITIONS OF APPROVAL IF ANY: \_\_\_\_\_

ACCEPTED FOR RECORD

**\*See Instructions on Reverse Side**

JAN 21 1983

**NMOCC**

WASHINGTON

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ well gas ☐ well other ☐
2. NAME OF OPERATOR  
Chace Oil Company, Inc.
3. ADDRESS OF OPERATOR  
313 Washington, SE, Albuquerque, NM 87108
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  
Unit 'I' - 1850' FSL & 790' FEL  
AT SURFACE:  
AT TOP PROD. INTERVAL:  
AT TOTAL DEPTH:
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐  
FRACTURE TREAT ☐  
SHOOT OR ACIDIZE ☐  
REPAIR WELL ☐  
PULL OR ALTER CASING ☐  
MULTIPLE COMPLETE ☐  
CHANGE ZONES ☐  
ABANDON\* ☐  
(other) *status*

☐  
☐  
☐  
☐  
☐  
☐  
☐  
☐  
☒

RECEIVED  
JAN 24 1983U. S. GEOLOGICAL SURVEY  
FARMINGTON, N. M.

Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

This sundry is to correct the field name to Chacon Dakota on all previous forms. There are no perforations or completions in the Pictured Cliffs, and no intention to perforate the Pictured Cliffs at this time.

Subsurface Safety Valve: Manu. and Type \_\_\_\_\_

18. I hereby certify that the foregoing is true and correct

SIGNED *E. W. Miller*

TITLE President

DATE 1/21/83

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_

TITLE \_\_\_\_\_

DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD

\*See Instructions on Reverse Side

JAN 21 1983

NMOCC

FARMINGTON

BY *gfb*