

Rita No. 2
Section 5, T23N, R6W
Rio Arriba County, New Mexico

SLOPE TESTS

Depth

Hole Deviation


232
1689
4318


1/4 °
1 °
1-1/4 °

State of New Mexico)
) ss
County of San Juan)

I, Steve S. Dunn, being first duly sworn, depose and state that the above and foregoing depth and hole deviation figures are true and correct to the best of my information and belief.

Subscribed and sworn before me this 13th day of April, 1982.




Notary Public

My Commission Expires 10/28/85