Form Approved. Budget Bureau No. 42-R1424

UNITED STATES DEPARTMENT OF THE INTERIOR

UNITED STATES	5. LEASE
DEPARTMENT OF THE INTERIOR	Jicarilla 71
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
	Jicarilla Apache
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
(Do not use this form for proposals to drill or to deepen or plug back to a diffi	지 나는 그는 그는 그를 만든 그는 그를 받는다.
reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME
1. oil gas	
	9. WELL NO.
2. NAME OF OPERATOR	71-7
Chace Oil Company, Inc. 3. ADDRESS OF OPERATOR	10. FIELD OR WILDCAT NAME
313 Washington, SE., Albuquerque, NM 87108	S. Lindrith - Gallup Dakota 1
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space	
below.) Unit "I" 2310' FSL & 990' FEL	Sec. 3, T23N,R4W
AT SURFACE:	12. COUNTY OR PARISH 13. STATE.
AT TOP PROD. INTERVAL:	Rio Arriba New Mexico
AT TOTAL DEPTH:	14. API NO. = = = = = = = = = = = = = = = = = = =
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTI	ICE,
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	7225' KB
TEST WATER SHUT-OFF	
FRACTURE TREAT	
SHOOT OR ACIDIZE	RECEIVE
REPAIR WELL	(NOTE: Report results of multiple completion or zone
PULL OR ALTER CASING	change on Form 9–330.)
CHANGE ZONES	JUL change on Form 9-330.)
ABANDON*	3, 1, 2
(other)	FINAMINGTON, N. W.
including estimated date of starting any proposed work. If well measured and true vertical depths for all markers and zones per Date of first delivery to El Paso Natural Gl:30 P. M.	tinent to this work.)*
	A TO A SECTION OF THE
Subsurface Safety Valve: Manu. and Type	San Company
	Set @ Ft
18. I hereby certify that the foregoing is true and correct	
SIGNED . W. President	DATE July 21, 1982
(This space for Federal or Sta	te office use)
	<u></u>
APPROVED BY TITLE TOTALL TOTALL TO THE CONDITIONS OF APPROVAL, IF ANY:	DATE
	recepted fin hecond
	1 St. of the 1 can be a second
*See Instructions on Reve	erse Side JUL 27 ISON

CARNELLETON EISTERT