

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ well gas ☐ well other ☐
2. NAME OF OPERATOR
Chace Oil Company, Inc.
3. ADDRESS OF OPERATOR
313 Washington, SE, Albuquerque, NM 87108
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
Unit "K" 2310' FSL & 2310' FWL
AT SURFACE:
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

- TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐

(other)
Spud

SUBSEQUENT REPORT OF

RECEIVED

SEP 28 1982

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

U. S. GEOLOGICAL SURVEY
FARMINGTON, N. M.

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Moved in and rigged up with Arapahoe Drilling Company. Spudded at 2:30 P. M. on 9-24-82. Ran 5 joints of 8 5/8" casing, 23#, K-55. Total length 215', set at 210.45 KB. Cemented with 150 sxs Class B cement, 3% calcium chloride, 1/4# Flocele. Circulated 5 sxs to surface. Plug down at 3:15 PM, 9-24-82.

Subsurface Safety Valve: Manu. and Type _____

18. I hereby certify that the foregoing is true and correct

SIGNED D. W. Meloy TITLE President DATE 9-27-82

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL: _____

*See Instructions on Reverse Side

FARMINGTON, N. M.

BY 527

NMOCC