

MERRION OIL & GAS CORPORATION

Rita Com No. 3
Sec. 15, T23N, R6W
Rio Arriba County, New Mexico

SLOPE TESTS

| <u>Depth</u> | <u>Hole Deviation</u> |
|--------------|-----------------------|
| 1277' | 3/4° |
| 1654' | 1 ° |
| 2478' | 1 ° |
| 3137' | 1/2° |
| 4921' | 1 ° |

RECEIVED
JUL 19 1983
OIL CON. DIV.
DIST. 3

State of New Mexico)
) ss
County of San Juan)

I, Steve S. Dunn, being first duly sworn, depose and state that the above and foregoing depth and hole deviation figures are true and correct to the best of my information and belief.

[Signature]

Subscribed and sworn before me this 13th day of July, 1983.

[Signature]
Notary Public

My Commission Expires Dec 11, 1985