Form 9-331 Dec. 1973

UNITED STATES

Form A	pproved	-	
Budget	Bureau	No.	42-R142

UNITED STATES	5. LEASE		
DEPARTMENT OF THE INTERIOR	NM 18946		
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME		
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME 8. FARM OR LEASE NAME		
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)			
1. oil 🙀 gas	<u>Celsius</u>		
well well other	9. WELL NO.		
2. NAME OF OPERATOR DUGAN PRODUCTION CORP.	10. FIELD OR WILDCAT NAME		
3. ADDRESS OF OPERATOR P O Box 208, Farmington, NM 87499	Counselors Gallup Assoc. 0 & G 11. SEC., T., R., M., OR BLK. AND SURVEY OR		
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA		
below.)	Sec. 14, T23N R6W		
AT SURFACE: 1890 FNL - 800 FEL AT TOP PROD. INTERVAL:	12. COUNTY OR PARISH 13. STATE Rio Arriba NM		
AT TOTAL DEPTH:	Rio Arriba NM		
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,			
REPORT, OR OTHER DATA REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF TEST WATER SHUT-OFF SHOOT OR ACIDIZE REPAIR WELL SHOOT OR ACIDIZE SHOOT OF THE SHOTT OF THE SHOOT OF THE SHOOT OF THE SHOTT OF THE SHOTT OF THE SHOT OF THE SHOTT OF THE SHOOT OF THE SHOTT OF THE SHOTT OF THE SHOT OF THE SHOTT OF THE SHOTT OF THE SHOTT OF THE SHOTT OF THE SHO	15. N EVATIONS (SHOW DF, KDB, AND WD)		
	6787' GL; 6799' RKB		
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF			
TEST WATER SHUT-OFF			
FRACTURE TREAT	λ		
SHOOT OR ACIDIZE LI REPAIR WELL	(NOTE Report results of multiple completion or zone SURVE change on Form 9–330.)		
MULTIPLE COMPLETE	CALN.M.		
CHANGE ZONES			
MULTIPLE COMPLETE CHANGE ZONES CHANGE ZONES COMPLETE SERVINGT CONTROL XX SurFace Casi	ng / anud		
(other) XX Surrace-casi	ng/ spud		
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is a measured and true vertical depths for all markers and zones pertine	directionally drilled, give substituace locations and		
4-28-83 227' W.O.C.			
MI & RU Four Corners Drilling Co.	rig #5. Spudded 12½" hole at		
8:00 p.m. 4-27-83. Ran 5 jts. 8-5			
T.E. 207' set at 219' RKB. Cement	ed with 135 sx class "B" plus-		
2% CaCl. (Total cement slurry 159 P.O.B. at 1:30 a.m. $4-28-83$. $\frac{1}{2}$ ° a	cu.ft.) Cement circulated.		
r.U.D. at 1:30 d.III. 4-20-03. 2 d	(33 , ½ at 103		
	•		
	• *		
Subsurface Safety Valve: Manu. and Type	Set @ Ft.		
18. I hereby certify that the foregoing is true and correct			
	DATE 4-28-83		
Jim L. Jacobs			
(This space for Federal or State o	necelled lon wellin		
APPROVED BY TITLE CONDITIONS OF APPROVAL, IF ANY:	DATE		
	MAY n e 1989		