5. LEASE

UNITED STATES DEPARTMENT OF THE INTERIOR

Subsurface Safety Valve: Manu. and Type	Set @Ft.
Subsurface Safety Valve: Manu. and Type	Set @ Ft.
3% Kcl. Circulated 7 bbls. c Plug down at 7:00 P. M.	of cement to surface.
4/30/83: Spudded at 3:00 P. M. with Ar Ran 5 joints of 8 5/8" 24# ca 216' KB. Cemented with 170 s	sing 202.16'. Set at
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly statincluding estimated date of starting any proposed work. If well is d measured and true vertical depths for all markers and zones pertinent	e all pertinent details, and give pertinent dates, irectionally drilled, give subsurface locations and it to this work.)*
PULL OR ALTER CASING	(NOTE: Report lessificat multiple completion or zone CAL SUM change on Form 9-330.) OIL CO. DIST. 3
TEST WATER SHUT-OFF	1983
REPORT, OR OTHER DATA REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF	15. ELEVATIONS (SHOW DF, KDB, AND WD) 7762' GL
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE	14. API NO.
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: Unit 'B', 517' FNL & AT TOP PROD. INTERVAL: 1913' FEL AT TOTAL DEPTH:	AREA Sec. 10, T23N,R4W 12. COUNTY OR PARISH 13. STATE Rio Arriba New Mexico
Chace Oil Company, Inc. 3. ADDRESS OF OPERATOR 87108 313 Washington, SE, Albuquerque, NM	10. FIELD OR WILDCAT NAME S. Lindrith Gallup Dakota 11. SEC. T. R. M. OR RIK AND SURVEY OF
1. oil gas other 2. NAME OF OPERATOR	Jicarilla Tribal Contract #71 9. WELL NO. 1/2-20
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	
SUNDRY NOTICES AND REPORTS ON WELLS	6. IF INDIAN, ALLOTTEE OR TRIBE NAME Jicarilla Apache 7. UNIT AGREEMENT NAME
GEOLOGICAL SURVEY	Tribal Contract #71

MAY 1 1983

DATE NECEPTED FOR RECORD

*See Instructions on Reverse Side

FARMINGTON DISTRICT