

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ gas ☐
well well other

2. NAME OF OPERATOR

Chace Oil Company, Inc.

3. ADDRESS OF OPERATOR

313 Washington, SE, Albuquerque, NM 87108

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

Unit 'F' - 1890' FNL & 1900' FWL

AT SURFACE:

AT TOP PROD. INTERVAL:

AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

CHANGE ZONES ☐

ABANDON* ☐

(other) ☐

SUBSEQUENT REPORT OF:

☐

☐

☐

☐

☐

☐

☐

☐

☐

Spud

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Spudded on 8/30/83 @ 4:15 P. M. with Arapahoe Drilling Company.
Ran 5 joints of 8 5/8", 24#, K-55 casing. 201' set @ 216' KB.
Cemented with 170 sks (200 CF) Class B neat, 3% calcium chloride,
1/4 lb/sk Flocele. Circulated 4 barrels to surface. Plug down
@ 8:45 P. M.

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

RECEIVED

SEP 09 1983

BUREAU OF LAND MANAGEMENT
FARMINGTON RESOURCE AREA

RECEIVED

SEP 13 1983

Subsurface Safety Valve: Manu. and Type

OIL CON. DIV.

Set @

Ft.

18. I hereby certify that the foregoing is true and correct

DIST. 3

SIGNED D. W. Miller TITLE President

DATE August 31, 1983

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____
CONDITIONS OF APPROVAL, IF ANY:

DATE _____

SEP 1 1983

*See Instructions on Reverse Side

NMOCC

FARMINGTON
FARMINGTON, NEW MEXICO

BY