5. LEASE Tribal Contract # 47

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
GEOLOGICAL SORVET	Jicarilla Apache
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
SUNDKY NUTICES AND INC. ON 15 ON WELLOS	
Do not use this form for proposals to drill or to deepen or plug back to a different eservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME
1. oil Say gas	<u>Jicarilla Tribal Contra</u> ct #47
well XX well other	9. WELL NO.
2. NAME OF OPERATOR	47-7-JV
Chace Oil Company, Inc.	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR New Mexico 87108	Chacon Dakota/Undes. Gallup 11. SEC., T., R., M., DR BLK. AND SURVEY OR
313 Washington, S.E., Albuguergue,	AREA
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	Sec. 13. T23N, R4W
below.) AT SURFACE: 790' FNL & 790' FEL	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL: Unit 'A'	Rio Arriba New Mexico
AT TOTAL DEPTH:	14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) 7385 GL; 7398 KB
	7389 GL; 7398; KB
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	
rest water shut-off	
FRACTURE TREAT	
SHOOT OR ACIDIZE	MOTE: Report results of multiple completion or zone
DILL OP ALTER CASING	change on Form 9-330.)
MULTIPLE COMPLETE	′ 1983
CHANGE ZONES	MANACEMENT
ABANDON* LI FARMINGTON REG	
(other) To correct previous reports	o a company of the co
Elevation should read: 7385' GL - 739	8' KB
Subsurface Safety Valve: Manu. and Type	
18. I hereby certify that the foregoing is true and correct	
SIGNED TITLE President	DATEOctober 13, 1983
(This space for Federal or State of APPROVED BY BUILDING TITLE	DATE
CONDITIONS OF APPROVAL, IF ANY:	ACCEPTED FOR RECORD
	OCŤ 2 G 1983
*See Instructions on Reverse	
See Management of the Control of the	FARMINGTON RESUSINGE AREA
	BY SMM
* * * * * * * * * * * * * * * * * * *	57