

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ well gas ☐ well other ☐

2. NAME OF OPERATOR
Chace Oil Company, Inc.

3. ADDRESS OF OPERATOR
313 Washington, S. E., Albuquerque, NM 87108

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: Unit 'F' - 1805' FNL & 2255' FWL
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐
(other) Spud ☐

☐
☐
☐
☐
☐
☐
☐
☐
☐

BUREAU OF LAND MANAGEMENT
FARMING PLANTATION AREA

RECEIVED (NOTE: Report results of multiple completion or zone change on Form 9-330.)
APR 30 1984

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Spudded at 3:00 P. M. on 4/23/84. Ran 5 joints of 8 5/8", 24# K-55, set at 224' KB. Cemented with 170 sks (200 CF) of Class B neat, 1/4# Flocele per sack, 3% calcium chloride. Circulated 4 barrels to surface. Plug down at 8:45 P. M.

RECEIVED
APR 30 1984

OIL COMPANY
DIST. 2

Subsurface Safety Valve: Manu. and Type _____

Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature] TITLE President DATE April 24, 1984

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RESOURCES

APR 27 1984

*See Instructions on Reverse Side

ADMINISTRATIVE RESOURCE AREA

RV

NMOCC



CHACE OIL COMPANY, INC.

313 Washington S.E.
Albuquerque, New Mexico 87108
(505) 266-5562

WELL HISTORY

NAME: Chace Oil Company, Inc.
Jicarilla Apache 71-23

LOCATION: Unit 'F' - 1805' FNL & 2255' FWL
Section 10, T23N, R4W
Rio Arriba County, New Mexico

ELEVATION: 7382' GR

<u>ESTIMATED FORMATION TOPS:</u>	<u>Revised</u>
Ojo	2667'
Pictured Cliffs	3065'
Chacra	3448'
Cliff House	4633'
Point Lookout	5173'
Gallup	5877'
Tocito	6892'
Greenhorn	7207'
Dakota 'A'	7302'
Dakota 'D'	7427'
Burro Canyon	7532'

PROPOSED DEPTH: 7632'

3/19/84:

APD Submitted.

4/4/84:

APD approved.

4/9/84:

Road and pad construction commenced.

Day #1. Present operation: WOC. Nipple up. Depth today: 225'. Rotary - RPM: 90. Weight on bit: all. Present drilling rate: 60'/hr. Pump - liner size: 5½. Pressure: 800. Strokes per minute: 60. Mud - spud. Mud additives: 30 gel. 3/4° @ 224'. Bit #1: 12¼, OSC 3; 225', 3½.

1 hour	Rig idle
3¼ hours	Move
4 hours	Rig up
1 hour	Drill rat and mousehole
3½ hours	Drilling surface
1 hour	Run casing
3/4 hour	Cement with Woodco
9½ hours	WOC. Nipple up.

4/23/84:

Spudded at 3:00 P. M. Ran 5 joints of 8 5/8" 24# K-55, set at 224' KB. Cemented with 170 sks. of Class B neat (200 CF), 1/4# Flocele per sack, 3% calcium chloride. Circulated 4 barrels to surface. Plug down @ 8:45 P. M. Arapahoe rig #11.