

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ well gas ☐ well other ☐

2. NAME OF OPERATOR

Chace Oil Company, Inc.

3. ADDRESS OF OPERATOR

313 Washington, SE., Albuquerque, NM 87108

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

Unit 'K' - 1650' FWL & 2310' FSL

AT SURFACE:

AT TOP PROD. INTERVAL:

AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

CHANGE ZONES ☐

ABANDON* ☐

(other) Spud ☐

SUBSEQUENT REPORT OF:

RECEIVED

MAY 07 1984

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

BUREAU OF LAND MANAGEMENT
FARMINGTON RESOURCE AREA

5. LEASE

Tribal Contract #71

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

Jicarilla Apache Tribe

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Jicarilla Tribal Contract #71

9. WELL NO.

71-24

10. FIELD OR WILDCAT NAME

South Lindrith, Gallup Dakota

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Section 10, T23N, R4W

12. COUNTY OR PARISH 13. STATE

Rio Arriba New Mexico

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)
7219' GR

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Spudded with Araphoe Drilling Company rig #10 at 2:00 P. M. on May 3, 1984. Ran five joints of 8 5/8", 24# casing - 219' set @ 232' KB. Cemented with 170 sacks (200 CF) of Class B neat, 3% calcium chloride, 1/4 lb/sk Flocele. Circulated 4 barrels to surface. Plug down @ 8:15 P. M.

RECEIVED
MAY 11 1984
OIL CON. DIV.
DIST. 3

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED J. W. Miller TITLE President DATE May 4, 1984

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD

MAY 10 1984

*See Instructions on Reverse Side

FARMINGTON RESOURCE AREA

RV



CHACE OIL COMPANY, INC.

313 Washington S.E.
Albuquerque, New Mexico 87108
(505) 266-5562

WELL HISTORY

NAME: Chace Oil Company, Inc.
Jicarilla Apache 71-24

LOCATION: Unit 'K' - 1650' FWL & 2310' FSL
Section 10, T23N, R4W
Rio Arriba County, New Mexico

ELEVATION: 7219' GR

ESTIMATED FORMATION TOPS:

Ojo	2402'
Pictured Cliffs	2820'
Chacra	3203'
Cliff House	4388'
Point Lookout	4928'
Gallup	5667'
Tocito	6682'
Greenhorn	7007'
Dakota 'A'	7102'
Dakota 'D'	7227'
Burro Canyon	7329'

PROPOSED DEPTH: 7429'

3/24/84:

APD submitted.

4/2/84:

APD approved.

4/23/84:

Road and pad construction commenced.

5/3/84:

Spudded with Arapahoe Drilling Company rig #10 at 2:00 P. M. Ran 5 joints of 8 5/8", 24# casing, 219' set @ 232' KB. Cemented with 170 sks (200 CF) of Class B neat, 3% calcium chloride, 1/4 lb/sk Flocele. Circulated 4 barrels to surface. Plug down @ 8:15 P. M.