

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE  
(Other instructions on reverse side)

Form approved  
Budget Bureau No. 1004-0135  
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR  
Chace Oil Company, Inc.

3. ADDRESS OF OPERATOR  
313 Washington, SE, Albuquerque, NM 87108

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface  
Unit 'F', 1761' FWL & 1873' FNL

14. PERMIT NO.

15. ELEVATIONS (Show surface of well)  
7375' GR

5. LEASE DESIGNATION AND SERIAL NO.  
Jicarilla Contract #47

6. IF INDIAN, ALLOTTEE OR TRIBE NAME  
Jicarilla Apache

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME  
Jicarilla Tribal Contract #47

9. WELL NO.  
17416

10. FIELD AND POOL, OR WILDCAT  
South Lindrith, Gallup Dakota

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA  
Section 13, T23N, R4W

12. COUNTY OR PARISH  
Rio Arriba

13. STATE  
New Mexico

RECEIVED  
MAY 28 1985

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	<input type="checkbox"/>	PULL OR ALTER CASING	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	MULTIPLE COMPLETE	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	ABANDON*	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	CHANGE PLANS	<input type="checkbox"/>
(Other)	<input type="checkbox"/>		

SUBSEQUENT REPORT OF:

WATER SHUT-OFF	<input type="checkbox"/>	REPAIRING WELL	<input type="checkbox"/>
FRACTURE TREATMENT	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
SHOOTING OR ACIDIZING	<input type="checkbox"/>	ABANDONMENT*	<input type="checkbox"/>
(Other) spud	<input type="checkbox"/>		

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Spudded with Arapahoe Drilling Company rig 11 at 2:30 p.m. on May 22, 1985. Ran 5 joints of 8 5/8" 24# casing, 215' set at 228'. Cemented with 170 sks (200 CF) of Class B cement, 1/4 lb/sk Flocele, 2% calcium chloride. Circulated 3 bbls to surface. Plug down at 8:30 p.m.

RECEIVED

MAY 31 1985

CON. DIV.  
DIST. 2

18. I hereby certify that the foregoing is true and correct

SIGNED D. W. Miller TITLE President DATE May 24, 1985

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD  
DATE

MAY 29 1985

\*See Instructions on Reverse Side

NMOCC

FARMINGTON RESOURCE AREA  
BY 8/15



# CHACE OIL COMPANY, INC.

313 Washington S.E.  
Albuquerque, New Mexico 87108  
(505) 265-2622

## WELL HISTORY

NAME: Chace Oil Company, Inc.  
Jicarilla Apache 47-16

LOCATION: Unit 'F', 1761' FWL & 1873' FNL  
Section 13, T23N,R4W  
Rio Arriba County, New Mexico

ESTIMATED FORMATION TOPS:

Ojo Alamo	2641'
Pictured Cliffs	3053'
Chacra	3401'
Cliff House	4575'
Point Lookout	5135'
Gallup	5837'
Juana Lopez	6853'
Greenhorn	7167'
Dakota 'A'	7249'
Dakota 'D'	7399'
Burro Canyon	7497'

PROPOSED DEPTH: 7575'      ELEVATION: 7375' GR

8/27/84:  
APD submitted.

8/28/84:  
APD approved.

5/13/85:  
Road and pad construction commenced.

5/22/85:  
Spudded with Arapahoe Drilling Company rig #11 at 2:30 p.m. on May 22, 1985. Ran 5 joints of 8 5/8" 24# casing, 215' set at 228'. Cemented with 170 sks (200 CF) of Class B cement, 1/4 lb/sk Flocele, 2% calcium chloride. Circulated 3 bbls. to surface. Plug down at 8:30 p.m.

RECEIVED  
MAY 31 1985  
W. L. OIL CO.  
ALBUQUERQUE, N.M.