GEOLOGICAL SURVEY	jicarilla Apache
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME
1. oil gas other Comingled	9. WELL NO.
2. NAME OF OPERATOR W.B. Martin & Associates, Inc.	#50 Martin-Whittaker
3. ADDRESS OF OPERATOR	10. FIELD OR WILDCAT NAME Wildcat
709 North Butler, Farmington, NM 87401 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	11. SEC., T., R., M., OR BLK. AND SURVEY OF
below.)	NE 1 Sec. 14/T23N/R4W
AT SURFACE: 940' FNL and 1700' FEL AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	12. COUNTY OR PARISH 13. STATE NM
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE.	14. API NO.
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	6755' GR
TEST WATER SHUT-OFF	
FRACTURE TREAT	
REPAIR WELL	(NOTE: Report results of multiple completion or zone
PULL OR ALTER CASING	change on Form 9-330)
CHANGE ZONES 🗍 🛗	
ABANDON•	
Gallup. The Dakota will not be perforated or coare applied for and approved. NOV 2 6 1984 CON DIST Subsurface Safety Valve: Manu. and Type 18. I hereby certify that the foregoing is true and correct	Set @Ft.
SIGNED On the Commander TITLE Operator Rep	D. DATE 11/26/84
(This space for Federal or State office	
APPROVED BY	DATE
$\bigcap A \in \mathcal{A}$	ACCEPTED FOR RECORD
*See Instructions on Reverse S	NOV 2 6 1984
	FARMINGTON RESOURCE AREA
	BY STATES