

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE
(Other Instructions on Re-
verse Side)

5. LEASE DESIGNATION AND SERIAL NO.
SF-078272
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME
8. FARM OR LEASE NAME
Dunn
9. WELL NO.
12
10. FIELD AND POOL, OR WILDCAT
Undesignated Dakota
Lybrook Gallup
11. SEC., T., R., W., OR BLK. AND SURVEY OR AREA
Sec 3 T23N R7W
12. COUNTY OR PARISH
13. STATE

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

RECEIVED

JUL 31 1985

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. NAME OF OPERATOR
BCO, Inc.
3. ADDRESS OF OPERATOR
135 Grant Avenue, Santa Fe, New Mexico 87501
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface
990' FSL 1800' FEL Sec 3, T23N, R7W, N.M.P.M., Rio Arriba County New Mexico
14. PERMIT NO.
15. ELEVATIONS (Show whether DF, ST, CR, etc.)

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	<input type="checkbox"/>	WATER SHUT-OFF	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	FRACTURE TREATMENT	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	SHOOTING OR ACIDIZING	<input checked="" type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	(Other)	<input type="checkbox"/>
(Other)	<input type="checkbox"/>	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	
PULL OR ALTER CASING	<input type="checkbox"/>	REPAIRING WELL	<input type="checkbox"/>
MULTIPLE COMPLETE	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
ABANDON*	<input type="checkbox"/>	ABANDONMENT*	<input type="checkbox"/>
CHANGE PLANS	<input type="checkbox"/>		

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

7/24/85 to 7/26/85 Drilled out DV Tools.

7/26/85 Ran Cement Bond Log Computer Laser. Tops will be reported at a later date. Pressure tested at 3500#'s and held for 30 minutes. Perforated with one 3 1/8" :32 shot at 6506, 6504, 6502, 6500, 6498.

7/29/85 Treated perfs with 1000 gallons 7 1/2% acid.

7/29/85 to 7/30/85 Tested perfs. Making slight gas cut water with slight cut of oil (est. 1/2 of 1% oil). Water is slightly salty and looks like water that was produced and later plugged at the Dunn 3 (offset well). Cannot pull water level below 6000' when swabbing. Well does not try to flow after swab gets out.

7/30/85 Obtained approval from John Keller to plug 6498-6506. See attached Sundry Notice for details of same.

Note: On Sundry filed June 26, 1985, it was reported that 4 1/2" casing was set at 6997'. Casing was actually set at 6597'.

RECEIVED

AUG 06 1985

DATE 7/30/85

18. I hereby certify that the foregoing is true and correct

SIGNED Elizabeth B. Keeshan TITLE Comptroller

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

OIL CON. DIV.

DIST. 3

DATE FOR RECORD

1985

*See Instructions on Reverse Side

NMOCC

FARMINGTON RESOURCE AREA