		/
Farm 9-331 Dec. 1973		Form Approved. Budget Sureau No. 42-71424
UNITED STATES		5. LEASE
DEPARTMENT OF THE INTERIOR		SF-078362
GEOLOGICAL SURVEY		6. IF INDIAN, ALLOTTEE OR TRUE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)		7. UNIT AGREEMENT NAME
1. oil gas cother well other		8. FARM OR LEASE NAME Marcus "A"
		9. WELL NO.
2. NAME OF OPERATOR Jack A. Cole		15
3. ADDRESS OF OPERATOR		10. FIELD OR WILDCAT NAME
P.O. Box 191, Farmington, N.M. 87499		Lybrook Gallup
4. LOCATION OF WELL (REPORT LOCATION CLEARLY, See space 17		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA NWNW
below.)		Sec. 1-T23N-R7W
AT SURFACE		12. COUNTY OR PARISHI 13. STATE
	O. INTERVAL: Same	Rio Arriba New Mexico
AT TOTAL DEPTH: Same		14. API NO.
	COPRIATE BOX TO INDICATE NATURE OF NOTICE.	
	OTHER DATA	15. ELEVATIONS (SHOW DF, KDB. AND WD) 6786 GR 6798 KB
REQUEST FOR A		
TEST WATER SHE		
SHOOT OR ACIDI	TO THE PROPERTY	FD
REPAIR WELL		(NOTE: Report results of multiple completion or zone
PULL OR ALIER CASING		
MULTIPLE COMPE		300
ABANDON*	BUREAU OF LAND MA	ALACEMENT
(other)	FARMINGTON RESOL	
including esti	ROPOSED OR COMPLETED OPERATIONS (Clearly state mated date of starting any proposed work. If well is did true vertical depths for all markers and zones pertinen	rectionally drilled give subsurface locations and
	Spud 5:30 P.M. Ran 6 joints 8 5/8, 24.0 lb., J-55 casing. Measured 252.68, landed at 264.68. Cemented with 250 sacks (295 cu. ft.) Class B, 3% CACl and 1/4 lb. Flocele per sack. Plug down 1:00 A.M. 10-15-86. Circulated cement to surface.	
10-15-86	Pressure test BOP to 500 psi for 15	
		A SEEDING

NMOC**C**

OCT 22 1986