

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPPLICATE*
(Other instructions on re-
verse side)

Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. ☐ OIL WELL ☒ GAS WELL ☐ OTHER

2. NAME OF OPERATOR
Chace Oil Company, Inc.

3. ADDRESS OF OPERATOR
313 Washington SE, Albuquerque, NM 87108

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface
Unit 'N'; 661' FSL & 1979' FWL

14. PERMIT NO.

15. ELEVATIONS (Show whether FORMATION RESOURCE AREA)
7379' GR

5. LEASE DESIGNATION AND SERIAL NO.
Jicarilla Contract #47

6. IF INDIAN, ALLOTTEE OR TRIBE NAME
Jicarilla Apache

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Jicarilla Tribal Cont. #47

9. WELL NO.
47-33

10. FIELD AND POOL, OR WILDCAT
S. Lindrith, Gallup-Dakota

11. SEC., T., R., M., OR B.L. AND SURVEY OR AREA
Section 12, T23N, R4W

12. COUNTY OR PARISH
Rio Arriba

13. STATE
New Mexico

RECEIVED

MAY 21 1987

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	<input type="checkbox"/>	PULL OR ALTER CASING	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	MULTIPLE COMPLETE	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	ABANDON*	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	CHANGE PLANE	<input type="checkbox"/>
(Other)	<input type="checkbox"/>		<input type="checkbox"/>

SUBSEQUENT REPORT OF:

WATER SHUT-OFF	<input type="checkbox"/>	REPAIRING WELL	<input type="checkbox"/>
FRACTURE TREATMENT	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
SHOOTING OR ACIDIZING	<input type="checkbox"/>	ABANDONMENT*	<input type="checkbox"/>
(Other) <u>spud</u>	<input type="checkbox"/>		<input type="checkbox"/>

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Spudded with Arapahoe Drilling Company Rig 11 at 4:30 P.M. on May 19, 1987.
Ran 5 joints 8 5/8", 24 lb./ft. casing 221 ft., set at 234' KB. Cemented with 170 sks (200 CF) Class B cement with 3% CaCl. Plug down at 9:15 P.M., 5-19-87.
Circulated 6 bbls. cement to surface.

RECEIVED
MAY 26 1987
OIL & GAS DIV.
DENVER

18. I hereby certify that the foregoing is true and correct

SIGNED Frank Walker TITLE Vice President DATE May 20, 1987

(This space for Federal or State office use)

ACCEPTED FOR RECORD

APPROVED BY _____ TITLE _____ DATE MAY 22 1987
CONDITIONS OF APPROVAL, IF ANY:

FARMINGTON RESOURCE AREA

BY Sam

*See Instructions on Reverse Side

NMOCC



CHACE OIL COMPANY, INC.

313 Washington S.E.

Albuquerque, New Mexico 87108

(505) 265-2622

WELL HISTORY

NAME:

Chace Oil Company, Inc.
Jicarilla Apache 47-33

LOCATION:

Unit 'N'; 661' FSL & 1979' FWL
Section 12, T23N, R4W
Rio Arriba County, New Mexico

ESTIMATED FORMATION TOPS:

Ojo Alamo	2610'
Picture Cliffs	3025'
Chacra	3375'
Cliff House	4575'
Point Lookout	5155'
Gallup	5855'
Tocito	6867'
Greenhorn	7170'
Dakota 'A'	7261'
Dakota 'D'	7401'
Burro Canyon	7505'

PROPOSED DEPTH:

7575'

APD SUBMITTED:

02/17/87

APD COMPLETE AS SUBMITTED:

02/23/87

APD APPROVED:

05/04/87