

N-11-23N-4W

Jic. Tr. Cont. 47 #21

CHACE OIL CO., INC.

J

30-039-24340

11-17-88

F. Loc. 782/S; 2189/W Elev. 7403 GL Spd. Comp. TD PB
 Casing S. @ W Sx. Int. @ W Sx. T. @ T Gas
 Csg. Perf. Prod. Stim.

Grav. 1st Del. Gas
 I.P. BO/D MCF/D After Hrs. SICP PSI After Days GOR 1st Del. Oil

TOPS		NiTD X	Well Log	TEST DATA							Ref.No.
Ojo Alamo		C-103	Plat X	Schd.	PC	Q	PW	PD	D		
Kirtland		C-104	Electric Log								
Fruitland			C-122								
Pictured Cliffs		Ditr	Dfa								
Chacra		Datr	Dac								
Cliff House											
Menefee											
Point Lookout											
Mancos											
Gallup											
Greenhorn											
Dakota											
Entrada											
			Acres 40								

S. Lin. Gal-Dak. Co. RA S 11 T 23NR 4W UN Oper. Chace Oil Co., Inc. Lse. Jic. Tr. Cont. 47 No. 21

JUN. 1 1 1990

SP-078765 (WC)
3162.3-1.0 (019)

CERTIFIED MAIL
P 140 431 372

RECEIVED

JUN 1 3 1990

OIL CON. DIV
DIST. 3

Chace Oil Company
313 Washington, SE
Albuquerque, NM 87108

Gentlemen:

Enclosed is your Application for Permit to Drill (APD) well No. 47-21 Jicarilla Tribal, SE/4SW/4, sec. 11, T. 23 N., R. 4 W., Rio Arriba County, New Mexico, Jicarilla Contract 47. As discussed with Frank Welker of your company on May 17, 1990, the subject APD is rescinded and returned due to drilling not being commenced within one year of the approval date.

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill site. If this office does not receive comment within 30 days, we will presume that no construction occurred and proceed accordingly. Later discovery that construction activities have in fact occurred, may result in assessment of liquidated damages.

Sincerely,

Ken Townsend

John L. Keller, Chief
FOR Branch of Mineral Resources

Enclosure

cc: New Mexico Oil Conservation Division, 1000 Rio Brazos Rd., Aztec, NM
87410

ABANDONED LOCATION