CHACE OIL CO., INC.

Sal. Dak. Co. RA 5 11

11-27-90 J 30-039-25029 F.Loc. 782/S: 2189/W Cu. ft. Cu. ft. Cu. ft. _Sx. Pr.. Casing 5. _Sx. Int.. T Gas Csg.Perf. Prod. Stim. ANS 1st Del. Gas Grav. BO/D 1st Del. Oil _PSI After_ MCF/D After Hrs. SICP_ Days GOR TEST DATA NITD Well Log TOPS Χ D Ojo Alamo Plat Schd. Q PW PD Ref.No. C-103 Х Kirtland C-104 Electric Log Fruitland C-122 Dfa Pictured Cliffs Ditr Chacra Dac Date Cliff House Menefee Point Lookout Mancos Gallup Greenhorn Dakota Entrada Acres 40

1 23N R 04W U N Oper. Chace Oil Co. Inc. Lee Jic. Tribal Ct. 47 No. 21



United States Department of the Interior

BUREAU OF LAND MANAGEMENT Farmington Resource Area 1235 Laplata Highway Farmington, New Mexico 87401



Jicarilla Contract 47 (WC) 3162.3-1.0 (019)

JAN 3 0 1992

Chace Oil Company, Inc. 313 Washington, S.E. Albuquerque, NM 87108

JAN31 1992 OIL CON. DIV

Gentlemen:

Enclosed are your Applications for Permit to Drill well Nos:

- No. 12 Jicarilla Tribal Contract 47, Section 11, T. 23 N., R. 4 W., Rio Arriba County, New Mexico
- 2. No. 21 Jicarilla Tribal Contract 47, Section 11, T. 23 N., R. 4 W., Rio Arriba County, New Mexico

As discussed with Charlotte McClanahan of your company on January 17, 1992, the subject APDs are rescinded and returned due to drilling not being commenced within one year of the approval date.

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill site. If this office does not receive comment within 30 days, we will presume that no construction occurred and proceed accordingly. Later discovery that construction activities have in fact occurred, may result in assessment of liquidated damages.

Sincerely,

John L. Keller

Chief, Branch of Mineral Resources

2 Enclosures

ce:

New Mexico Oil Conservation Division, 1000 Rio Brazos Rd., Aztec, NM 87410 BIA, Jicarilla Agency, P.O. Box 167, Dulce, NM 87528

