



UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe, New Mexico
Lease No. NM, 029930-A
Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

| | |
|------------------------------------------------|--------------------------------------------|
| NOTICE OF INTENTION TO DRILL | SUBSEQUENT REPORT OF WATER SHUT-OFF |
| NOTICE OF INTENTION TO CHANGE PLANS | SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING |
| NOTICE OF INTENTION TO TEST WATER SHUT-OFF | SUBSEQUENT REPORT OF ALTERING CASING |
| NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL | SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR |
| NOTICE OF INTENTION TO SHOOT OR ACIDIZE | SUBSEQUENT REPORT OF ABANDONMENT |
| NOTICE OF INTENTION TO PULL OR ALTER CASING | SUPPLEMENTARY WELL HISTORY |
| NOTICE OF INTENTION TO ABANDON WELL | |

Well No. 1-X-98 is located 790' ft. from [N] line and 330' ft. from [W] line of Section

SW/4, NW/4, NW/4 15N, 3W NMPM.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

wildcat Sandcoal New Mexico
(Field) (County or Subdivision) (State or Territory)

SEP 27 1967

The elevation of the derrick floor above sea level is 6004.6 ft.

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

hole left open (see details our log & "intent to abandon" forms) with water coming out (under Artesian pressure?) at rate of approximately 25 gallons a minute - Good water being drinkable to man or beast, alike.

Awaiting action from Bureau of Land Management, USGS & rancher regarding disposition of water, prior to taking further steps, ~~as suggested~~.

as cementing & plugging, as suggested - Kindly advise what you want me to do.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Jenge Semutovich
Address 121 Valley Drive,
Santa Fe, New Mexico.

By Same as
Title operator