


(5)

Form 9-331a
(Feb. 1961)



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Budget Bureau No. 42-R358.4.
Form Approved.

Land Office Santa Fe, New Mexico

Lease No. N/M 029930-A

Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

RECEIVED

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

7 October, 19 62

Well No. 41 # 1-1 is located 790 ft. from N line and 330' ft. from B line of sec. 3


NW/4, NW/4 (1/4 Sec. and 1/4 Sec. No.) 15 N, 3 W (Twp.) (Range) N. M. P. M. (Meridian)
Wilcox (Field) Sandoval (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 6004.6 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Filled hole around surface casing with earth, and cemented over. Filled surface casing with cement, as far as it would go (with water so close to surface in pipe), and cleaned up site.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Gerge Semutovich
Address 121 Valley Drive,
Santa Fe, New Mexico

By Same as -
Title operator -