

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Alamogordo, NM.

Lease No. NM. 629930

Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

RECEIVED
FEB 19 1962

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

15 October, 1961

Well No. 9A #1 is located 740' ft. from [N] line and 330' ft. from [E] line of sec. 3


S1/4, NW1/4, NW1/4 (1/4 Sec. and 1/4 Sec. No.) 15 N, 3 West (Twp.) NM PM. (Meridian)
Wilcox (Field) Hudon (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 6004' ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

No was cut as yet / not yet in Dakota) = but electrical log was run to present TD of 920'.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Jenge-Semantic

Address 121 Valley Drive, Alamogordo, NM.

By Same as

Title operator