


Resp. 1-7-66
P.J.H.

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND SURVEY



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE TO BE	SUBSEQUENT REPORT OF WATER SHUT OFF
NOTICE OF INTENTION TO CHANGE PUMP	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO REPAIR OR REPAIR WELL	SUBSEQUENT REPORT OF RE DRILLING OR REPAIR
NOTICE OF INTENTION TO SHUT OFF OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

PLEASE PRINT OR CHECK MARKS NATURE OF REPORT, NOTICE, OR OTHER DATA

Well No. 740111 N 1/4 Sec 20 T1N R10E S10E

Alameda Sanseval New Mexico

DETAILS OF WORK

Well was drilled to 910', lost winter, and temporarily abandoned due to other conditions (1. no water test). When we tried to clean out hole, we found to our surprise the surface pipe had tampered with, and pulled out, but also that foreign objects had been dumped into hole, making it impossible for us to progress beyond 620', at this level we used the drillbits trying to get through the net & obstruction, hole was therefore plugged with cement plug, as per instructions, its filled, site cleaned up, and abandoned. I am presently strongly considering taking legal action against "persons unknown" for deliberate damage to my drilling.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company _____
Address 121 Valley Drive
Santa Fe, New Mexico.
By _____
Title _____

