


(SUBMIT IN TRIPLICATE)



APPROVED
UNITED STATES
DEPARTMENT OF THE INTERIOR
NOV 1962 GEOLOGICAL SURVEY

P. T. McGRATH

Land Office _____
Lease No. NM 029930-A
Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	X
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

10 October, 1962


Well No. GS#X-2 is located 590' ft. from ~~330~~ ^(N) line and 610' ft. from ~~330~~ ^(W) line of sec. 3
NW ~~4~~, NW ~~4~~, NW ~~4~~ 15N, 11W N.M.P.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
wildcat Sandoval New Mexico.
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6025' ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Plugged 5 1/2" casing with 100' cement plus, and cleaned up side.



RECEIVED

OCT 17 1962

U. S. GEOLOGICAL SURVEY
FARMINGTON, NEW MEXICO

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

~~Company~~ George Senutovitch
Address 121 Valley Drive, Santa Fe, NM.

By same as
Title operator