


Form 9-331a
(Feb. 1951)

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 134986
Unit _____



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	X
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	X
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

November 22, 19 61


Well No. 41-26 is located 560 ft. from N line and 60 ft. from E line of sec. 26
NE 26 (1/4 Sec. and Sec. No.) 17N (Twp.) 3E (Range) N.M.P.M. (Meridian)
Wildcat (Field) Sandoval (County or Subdivision) New Mexico (State or Territory)

The elevation of the Well above sea level is 6339.9 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

DST #1 3400-3511 (Intake) ISI 1 hr., open 2 hr., PSI 2 hrs. strong blow decreasing to fair. No gas to surface. Recovered 2747' (29.4 bbls.) mud cut water. ISIP/PSIP 144/144. IFP/FFP 235/122 HP (73/175).



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Shell Oil Company
Address P. O. Box 120
Farington, New Mexico

Original Signed By
W. M. MARSHALL
By W. M. Marshall
Title Division Exploitation Engineer