

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office SANTA FE, N.M.

Lease No. 2101171

Unit 1

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	<u>FEB 3 1960</u>
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

RECEIVED

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

....., 1959

Well No. 1 is located 1650 ft. from N line and 990 ft. from E line of sec. 33

33 (1/4 Sec. and Sec. No.) 10N (Twp.) 2W (Range) R2M (Meridian)

BLISS (Field) SANDOVAL (County or Subdivision) NEW MEXICO (State or Territory)

The elevation of the derrick floor above sea level is 6003.6 ft.


DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

This well was completed and casing cemented on October 15, 1959. 33 sacks of cement were pumped into 5-1/2" casing and circulated. Apparent water cut off was obtained.

340 ft. of 2" tubing has been installed in the 5-1/2" casing. Pump jack has been installed and 100 bbls of oil storage has been installed and pumping operations are in effect.

ILLEGIBLE



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company G.S. HARVEY J.I. HARVEY, OPERATOR

Address 437 Camino Del Monte Sol
Santa Fe, New Mexico

By J.I. HARVEY
G.S. HARVEY
Title _____

Faint, illegible text in the top left corner, possibly a header or address.

