


Form 9-331a  
(Feb. 1951)



(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office 2.2.33112-1

Lease No. 2.2.33112-1

Unit RECEIVED

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)


Well No. 2 is located 600 ft. from N line and 100 ft. from E line of sec. 21  
21 (Sec. and Sec. No.) 100 (Twp.) 20 (Range) 100 (Meridian)  
Willamette (Field) Washington (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 600 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Well was drilled with rotary rig & 3/4" diameter hole to a total depth of 210 feet. No oil of commercial value was found and it has been decided to abandon the well. Telephonic permission was requested and granted to plug the well. Instructions as to plugging were given.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company J. L. Murray

Address 477 Madison Ave, Santa Fe, N. Mex.

By J. L. Murray

Title Operator

