Form 9-331a (Feb. 1951)	(SUBMIT IN TRIPLICATE)
	DEPARTMENT OF THE INTERIOR
•	1897. 3 GEOLOGICAL SURVEY

Approval expires 12-31-60.	
Santa Fe, N. i	4.
Land Office SP 081160-F	
Loase No.	
Unit	

SUNDRY NOTICES AND REPORTS ON WELLS

|--|

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

and the second of			April 13		19
Well No is located NW 1/4 SW 1/4	1435 ft. from.		1155 ft. from	W line of sec.	21
Wildcat (1/4 Sec. and Sec. No.)	(Twp.) Sa ndo va l	(Range)	(Meridian)	ew Mexico	
(Field)	(County of	r Subdivision)	(St	ate or Territory)	

The elevation of the derrick floor above sea level is 6683 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

A 6-5/8" hole was drilled to a total depth of 1000 feet with rotary drill. 4-1/2" pipe was set to 973 feet and cemented by the Dowell Company a successful cut off was effected. The well was then perforated by the Welex Company from 658' to 668' and from 764' to 774'. The well was then swabbed for 48 hours and produced 4 barrels of 36 gravity oil the first 24 hours and 8 barrels of 36 gravity oil the second 24 hours. Due to unpassable roads and inclement weather the well was not pumping in March, but tubing and reds are now being placed in the well and pumping jack is on location and this well will be producing into the tanks by April 16th. Tanks and treater are installed. Thirty Two feet of 8-5/8" surface casing set with cemeat.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company	Francis L. Harvey		
Address	Box 990 Wichita Falls, Texas		
		By Franco Hou	محم
		Title Owner	
			,